

General Environmental Incident Summary

Incident: 4119 **Date/Time Notice:** 6/6/2016

DEM Incident No:

Responsible Party: DLC

Date Incident: 6/4/2016

Time Incident:

Duration:

County: Dunn

Twp: 147

Rng: 96

Sec: 34

Qtr:

Lat: 47.50250

Long: -102.90440

Method: Navigation quality GPS

Location Description: Bear Creek NGL Pipeline Spread 1 station# 518+50

Submitted By: Chase Edmiston

Affiliation:

Address: 100 W 5th St

City: Tulsa

State: OK

Zip:

Received By:

Contact Person:

2729 Paintball Way
Bismarck, ND

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: hydraulic line rupture

Description of Released Contaminant: hydraulic oil

Volume Spilled:

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

hydraulic hose ruptured while crew was moving bore rig

Risk Evaluation:

None

of Fatalities:

of Injuries:

Affected Medium: 03 - soil

Potential Environmental Impacts:

Localized area of soil was contaminated. No other impacts

Action Taken or Planned:

Oil was immediately contained and cleaned up. Approximately 8 cubic feet of subsoil was recovered and transported to approved landfill

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 6/7/2016 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Volume:

Notes:

According to the report there was a release of hydraulic fluid. Further follow-up needed.

Date: 8/4/2016 **Status:** No Further Action Requested

Author: Washek, Sandi

Updated Volume: 0.50 gallons

Notes:

Arrived on site at 10:42 a.m. accompanied by company representative. Weather was overcast with temperature of 69 degrees F. A hydraulic hose broke while the crew was moving the boring rig. The impacted soil is located in pasture land. Inspection of the area showed no visible staining of the soil. No water was impacted. The area has been leveled and was in the process of being seeded. No additional follow-up needed.